



The Public Health and Safety Organization

## NSF Product and Service Listings

These NSF Official Listings are current as of **Friday, August 20, 2021** at 12:15 a.m. Eastern Time. Please [contact NSF](#) to confirm the status of any Listing, report errors, or make suggestions.

Alert: NSF is concerned about fraudulent downloading and manipulation of website text. Always confirm this information by clicking on the below link for the most accurate information: <http://info.nsf.org/Certified/PwsComponents>Listings.asp?Company=0B020&Standard=061&>

---

### NSF/ANSI/CAN 61 Drinking Water System Components - Health Effects

**NOTE: Unless otherwise indicated for Materials, Certification is only for the Water Contact Material shown in the Listing.**  
**Click here for a list of [Abbreviations used in these Listings](#). Click here for the definitions of [Water Contact Temperatures denoted in these Listings](#).**

---

Subor Boru Sanayi Ve Ticaret A.S.

Ahmetler Mahallesi

Karapurcek 54430 Sakarya

Turkey

90 264 471 61 00

[Visit this company's website](#) (<http://www.subor.com.tr>)

(<http://www.subor.com.tr>)

**Facility :** Sakarya, Turkey

**Pipes and Related Products**

Trade Designation	Size	Water Contact Temp	Water Contact Material
<b>Pipe[1]</b>			
Subor GRP Pipe	300 - 4000 mm	CLD 23	FRP

[1] Only products bearing the NSF Mark on the product, product packaging, and/or documentation shipped with the product are Certified.

**Fittings[1]**

Subor GRP Elbows	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Flanges	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Tee's	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Reducers	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Spools	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Tanks	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Couplings	300 - 4000 mm	CLD 23	MLTPL
Subor GRP Manholes	300 - 4000 mm	CLD 23	MLTPL

[1] Only products bearing the NSF Mark on the product, product packaging, and/or documentation shipped with the product are Certified.

---

Number of matching Manufacturers is 1

Number of matching Products is 9

Processing time was 0 seconds